

PROJECT 10073 RECORD CARD

1. DATE DR 6 May 64		2. LOCATION Yellow Springs, Ohio		12. CONCLUSIONS ☐ Was Balloon ☐ Probably Balloon ☐ Possibly Balloon ☐ Was Aircraft ☐ Probably Aircraft ☐ Possibly Aircraft ☐ Was Astronomical ☐ Probably Astronomical ☐ Possibly Astronomical ☒ Other Part of B-57 crash ☐ Insufficient Data for Evaluation ☐ Unknown	
3. DATE-TIME GROUP Local 1830 GMT _____		4. TYPE OF OBSERVATION ☒ Ground-Visual ☐ Ground-Radar ☐ Air-Visual ☐ Air-Intercept Radar			
5. PHOTOS ☐ Yes Phys Spec ☒ No		6. SOURCE civilian			
7. LENGTH OF OBSERVATION n/a		8. NUMBER OF OBJECTS two			
9. COURSE n/a					
10. BRIEF SUMMARY OF SIGHTING Call from individual with pieces of metal found on farm about 4' x 5' painted green and yellow.				11. COMMENTS Witness contacted and matter turned over to Base command post. Metal part of crashed B-57.	

HEADQUARTERS
FOREIGN TECHNOLOGY DIVISION
AIR FORCE SYSTEMS COMMAND
UNITED STATES AIR FORCE
WRIGHT-PATTERSON AIR FORCE BASE, OHIO



6 May 1954
Yellow Springs, Ohio

REPLY TO
ATTN OF: TDX

SUBJECT: Extract from Duty Officer Report

7 May 64

TO: TDEW

The following, extracted from Capt Hartke's OD Report dated 6 May 64, is quoted for your information:

1830 hours, Received call from [REDACTED] (b) in Yellow Springs. She reported that [REDACTED] (b) a worker on her farm, found 2 pieces of aluminum approximately 4' X 5' painted green and yellow on her farm. I told her that I would check into the matter and that I would accept the charge for the phone call. However, the exchange supervisor informed me that the call was placed on automatic equipment and would be charged to Mrs. [REDACTED] bill. I called the ASD Command Post who called Mr. [REDACTED] and turned the matter over to the Base Command Post. Contact Airman Sargent for any other details.

Robert A. Callanan

ROBERT A. CALLANAN
1st Lt, USAF
Asst Administrative Officer

Part of B-57 that crashed